

FEDERAL ENERGY REGULATORY COMMISSION
Office of Energy Projects
Division of Dam Safety and Inspections - Chicago Regional Office
230 South Dearborn Street, Suite 3130
Chicago, Illinois 60604
(312) 596-4430 Office - (312) 596-4460 Facsimile

In reply, refer to: P-2785

May 13, 2014

Mr. Lee Mueller
Boyce Hydro Power, LLC
4132 S. Rainbow Blvd. #247
Las Vegas, Nevada 89103


**Re: Part 12.10(a) Emergency Retaining Wall Repair
Sanford Hydroelectric Project – FERC No. 2785**

Dear Mr. Mueller:

We have received your April 30, 2014 Part 12.10(a) report concerning erosion of the right embankment toe around the bag riprap headwall during the April 13, 2014 spring runoff event at your Sanford Hydroelectric Project (P-2785). The bag riprap headwall was installed in 1929 due to a similar runoff event that created erosion along the downstream embankment toe. As part of your 2014 emergency repairs, you constructed a concrete wing wall downstream of the bag riprap headwall. The design was submitted on April 28, 2014. A final construction report of the concrete wing wall protection should be submitted by **July 18, 2014**. These improvements should be included in your 2015 supporting technical information document updates.

Please contact Peter Chapman, P.E. at (312) 596-4446 or me at (312) 596-4437 if you have questions concerning this letter.

Sincerely,


John A. Zygaj, P.E.
Regional Engineer

CC:
Mr. Frank Christie, P.E., General Manager
Boyce Hydro Power, LLC
P.O. Box 15
Edenville, MI 48620

Document Content(s)

13550728.tif.....1-1