

# ***BOYCE HYDRO POWER, LLC***

A W.D. Boyce Trusts Legacy Enterprise  
Stephen B. Hultberg & Lee W. Mueller, Co-Member Managers  
6000 S. M-30 (P.O.Box 15)  
Edenville, MI 48624  
tel: (989) 689-3161 / fax: (989) 689-3155

March 21, 2011

Ms. Peggy A. Harding, PE  
Regional Engineer  
Federal Energy Regulatory Commission  
230 S. Dearborn St., Suite 3130  
Chicago, IL 60604

Re: Sanford Embankment Toe drain  
P-2785

Dear Ms. Harding:

This month we have completed approximately 125 feet of additional reverse toe filter construction at the right Sanford embankment. Ninety feet was the minimum required. We have approximately 115 feet left to construct to have everything right of the fuse plug completed. We do not have enough material left to finish this 115 feet, but do have enough to complete the piping and backfill in the ditch. Enclosed you will find a sketch of what this work would consist of. If we proceed with this ditch work now, we would anticipate finishing the complete filter work in the next one or two years.


We are submitting this proposal for your review and comment.

Sincerely,  
Boyce Hydro Power, LLC



Frank O. Christie, PE  
General Manager

cc: Lee W. Mueller  
Stephen Hultberg  
Steve Doret



**SANFORD DAM**  
**EMBANKMENT DETAIL**

SCALE: 1" = 3'